



**LONGFELLOW DRILLING, INC.**

RR 1, BOX 123 CLEARFIELD, IOWA 50840  
(515) 336-2297

Earlham, Iowa Well No. 4  
Drill Log 9-22-86

Sample No.	Depth		Thickness	Description of Beds
	From	To		
1	0'	8'	8'	Fill Material, Sandy Clay
2	8'	12'	4'	Fine Dry Sand
3	12'	17'	5'	Grey Brown Sandy Silt
4	17'	24'	7'	Grey Silt
5	24'	26'	2'	Silt and Coarse Sand
6	26'	29' 4"	3' 4"	Coarse Sand
7	29' 4"	37' 3"	7' 11"	Coarse Sand and Cobbles, 6"+
8	37' 3"	41' 6"	4' 3"	Fine Grey Blue Sand
9	41' 6"	43'	1' 6"	Blue Glacial Till